Dart Aerospace Ltd. Monday, 17/03/2008 12:29:55 PM User. Linda Lacelle **Process Sheet** 0803.18 : CU-DAR001 Dart Helicopters Services : 38067 - 2 **Drawing Name** Customer Job Number **Estimate Number** : 10437 : D33191 Part Number P.O. Number : D3319 REV. B : 17/03/2008 S.O. No. : **Drawing Number** This Issue : N/A : NC Project Number Prsht Rev. : B : SMALL /MED FAB : // **Drawing Revision** Type First Issue : 35856 Material Previous Run Each Qty: **Due Date** : 24/03/2008 Written By Checked & Approved By KJ/EC 05.10.14 B Added step 9, dwg rev B Comment : Est: Est Rev:C Now on Waterjet 06-10-26 JLM Additional Product Job Number: Seq. #: Machine Or Operation: Description: 1010/1025/A21/6aA SHEET .048 1.0 M1010S18GA Comment: Qty.: 0.6594 sf(s)/Unit Total: 6.5940 sf(s) 1010/1025/A21/6aA SHEET .048 M105084 Batch: 10.3 0 0 1 WATER JET 2.0 Comment: FLOW WATER JET 1-Cut as per Dwg D3319 Dwg Rev: IR 8-3-17 Prog Rev:_ 2-Deburr if necessary INSPECT PARTS AS THEY COME OFF MACHINE 3.0 IR 8-3-17 Comment: INSPECT PARTS AS THEY COME OFF MACHINE SECOND CHECK 4.0 (410) Comment: SECOND CHECK SMALL FAB 1 SMALL & MEDIUM FAB RESOURCE 1 5.0 Comment: SMALL & MEDIUM FAB RESOURCE 1 Deburr if necessary

Page 1

Form: rprocess

Mondey, 17/03/2008 12:29:55 PM Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: WEARPLATE Job Number: 38067 Part Number: D33191 Job Number: Seq. #: Machine Or Operation: Description: 6.0 BRAKE NC NC BRAKE Comment: NC BRAKE 1- Form using DT8326 & DT8261 as per Dwg D3319 Rev: 2- Form flat on press using DT8776 block 7.0 QC6 DIMENSIONAL CHECK Comment: DIMENSIONAL 8.0 LARGE FAB 1 LARGE FABRICATION RESOURCE 1 Comment: LARGE FABRICATION RESOURCE 1 1- Layout weld location as per Dwg D3319 using jig D3319-1T3 2- Weld hard surface using D3319-1T2 per QSI 004 and Dwg D3319 Rev: Qty Part Number Description 08-03-1814 A/R N/A 7560 Hardcoat Rod 9.0 VISUAL WELDING INSPECTION Comment: VISUAL WELDING INSPECTION 10.0 POWDER COATING 106442 Comment: POWDER COATING Powder Coat Grey Sandtex (Ref: 4.3.5.6) as per QSI 005 4.3 11.0 QC3 Comment: INSPECT 12.0 PACKAGING 1 PACKAGING RESOURCE #1

Comment: PACKAGING RESOURCE #1

Identify on inside surface using a permanent fine point marker with the following:

TCCA-PDA, Dart Aerospace Ltd.

P/N; D3319-1, B/N: BXXXXX

For Product Eligibility see PDA05-18

and Stock Location:_ 8/31/18 54 (42)

Monday, 17/03/2008 12:29.55 PM Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: WEARPLATE

Job Number: 38067

Part Number; D33191

Job Number:



Seq. #:

Machine Or Operation:

Description:

13.0

QC21

Comment: FINAL

FINAL INSPECTION/W/O RELEASE

08/03

Job Completion



TION/W/O RELEASE

- 2008/3/18



Dart Aeros	pace	Ltd
------------	------	-----

erospace L	.td						
		W	ORK ORDER CHANGE	S			
STEP	PROCEDURE CHANGE				Date Q	ty Approval Chief Eng / Prod Mgr	Approval QC Inspector
:	PAR #:	Fault Cateç	gory:				
		WORK OPP	D NON CONTEST	QA: N/	C Closed: _	Date: _	
				CE (NCR)			- O. T.
STEP	Description of NC Section A	Initial	Action Description		Verificatio		Approval
		Chief Eng	Chief Eng	Date	Section C	Chief Eng	QC Inspector
							j
							1
	66						
	STEP	PAR #:	STEP PROCEDURE CHA PAR #: Fault Categ WORK ORDE	WORK ORDER CHANGE PROCEDURE CHANGE PAR #: Fault Category: WORK ORDER NON-CONFORMAN STEP Description of NC	WORK ORDER CHANGES STEP PROCEDURE CHANGE By PAR #: Fault Category: NCR: Yes N QA: N/ WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC Section A Corrective Action Section B Initial Action Description Sign &	STEP PROCEDURE CHANGE By Date Q PAR #: Fault Category: NCR: Yes No DQA: QA: N/C Closed: WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC Section A Description of NC Section A Corrective Action Section B Corrective Corrective Action Section B Corrective Correc	STEP PROCEDURE CHANGE By Date Qty Approval Chief Eng/Prod Mgr PAR #: Fault Category: NCR: Yes No DQA: Date: QA: N/C Closed: Date: QA: N/C Closed: Date: VORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC Section A Description Sign & Section C Content or Section A Description Section B De

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order:	38667		
Description: WEAR PLATE	Part Number:	D3319-1		
Inspection Dwg: 033/9-1 Rev: 5		Page 1 of 1		

	x	First Arti	cle	Proto	type	×
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
316	4,006001	.317	*			
1	1.005 - 601	1547	*			
.670 14	1007830	-673	*			8
1,600 4	0:0	1.603	*			
	00	3.816	¥		1	
3.563	010	3.563	¥			
4.712 4		4.707	*			
	G(0): -		*			
3.190 +	oro		*			
3 660 4	cio	2.665	*			
	0i0		*			74
11.942 4	00		¥		-	
16.100 4.	010.	Total Control of the	*			
19.09 4.		18.69	×		10	
,60 t/.	030	.60	*			
	-					3 y
ured by: B	Aud	lited by:		Proto	type Approval:	Tu/
-	3-17	- 1 0	10/10		Date:	1
	nge		144/5	I L	Revised	1.10

Dart	A -		-		1 4-4	
Dart	Ae	OS	Da	ce	Lu	

Dart Ae	rospace Ltd								
W/O:			WORK ORDER	CHANGES					
DATE	STEP	PR	OCEDURE CHANGE		Ву [Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Category:	NCR:	Yes No	DQ	A:	_ Date: _	
				-	QA: N/C	Close	d:	_ Date: _	
NCR:			WORK ORDER NON-COM	IFORMANCE (NCR)				

NCR:			WORK ORDE	ER NON-CONFORMAN	CE (NCR)			
		Description of NC		Corrective Action Section B	Verification	Approval	Annewal	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	Approval QC Inspector

NOTE: Date & initial all entries